


TUB/SHOWER/HAND SHOWER TRIM MODEL: 0488-3506-T736-2.0-TRM INSTALLATION GUIDE



FEATURE HIGHLIGHTS

Tub/Shower/Hand Shower Trim shall include metal lever handles, shower arm with decorative flange, hand shower coupling with flange, in-line vacuum breaker, non-diverter tub spout, ADA 1 mode hand shower and 1 mode showerhead with 2.0 gpm (7.6 L/min) flow restrictors.

Tub/Shower/Hand Shower Trim shall be metal construction plated in standard polished chrome finish.

MODIFICATIONS

☐ **-1.75 CG** 1.75 gpm (6.6 L/min) flow restrictor

Note: Append appropriate -suffix to model number.

COMPLIANCE


- ASME A112.18.1/CSA B125.1
- ASSE 1014 (in-line vacuum breaker for back flow protection)




WARRANTY

5 Years - for industrial/commercial installations. Refer to symmons.com/warranty for complete warranty information.

DIMENSIONS



INSTALLATION/PARTS BREAKDOWN



Item	Description	Part Number
1 2	Flange Shower Arm	300S
3	Showerhead 2.0 Showerhead 1.75	532SH-2.0 532SH-1.75
4 5 6	Mounting Plate Mounting Screws Diverter Escutcheon	T-416A
7	Dome Cover	T-19
8 9	Handle Set Screw	T-242A
9	Set Screw	S2H-8D
10 11 12	Mounting Plate Mounting Screws Shower Escutcheon	T-237NSP- K002
13	Tub Spout	067
14	Wall Elbow	FP-40
15 16	Vacuum Breaker 60" Hose	EF-104
17	Slide Bar Assembly	T-600B-36
18	Hand Shower 2.0 Hand Shower 1.75	ADACHS-2.0 ADACHS-1.75
19	Slide Mechanism	FP-SM6
	Tools Doguiro	

Tools Required		
Adjustable Wrench		
Allen Wrench: Handle (3/16")		
Phillips Head Screwdriver		
Plumber Tape		
Silicone		

Notes:

- 1) Apply a bead of silicone around the perimeter of all shower trim installed flush to the finished wall (less mounting plates and brackets). Leave opening on bottom of escutcheon for weep hole.
- 2) Apply plumber tape to threaded connections as necessary. DO NOT use plumber tape on fittings with face seal washers or o-rings.

⚠ **WARNING:** This product can expose you to chemicals including lead, which is known to the state of California to cause cancer, birth defects, or other reproductive harm. For more information, go to www.P65Warnings.ca.gov.